

# Oil Field Environmental Incident Summary

**Incident:** 20130115112850      **Date/Time of Notice:** 01/15/2013 11:07

**Responsible Party:** ConocoPhillips

**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Name:** CHSU 24C-3SH 16

**Field Name:** CEDAR HILLS

**Well File #:** 15953

**Date Incident:** 1/14/2013      **Time Incident:** 13:00

**Facility ID Number:**

**County:** BOWMAN

**Twp:** 131

**Rng:** 106

**Sec:** 3

**Qtr:** SE SW

**Location Description:** On the right of way belonging to the CHSU 24C-3NH 16, ½ mile south of the wellhead.

**Submitted By:** Lewis Schoenberger

**Received By:**

**Contact Person:** Lewis Schoenberger  
PO BOX 51810  
MIDLAND, TX 79710-1810

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Miles

**Distance Nearest Water Well:** 0.5 Miles

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** Yes - On Pipeline ROW

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	barrels	0.5	barrels	0.5	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 8/18/2016

**Clean Up Concluded:** 10/24/2013

**Risk Evaluation:**

**Areal Extent:**

**Potential Environmental Impacts:**

**Action Taken or Planned:**

The flow line was isolated. The leaking oil was vacuumed up by the hydrovac unit.

**Wastes Disposal Location:** At an appropriate disposal facility

**Agencies Involved:**

**Updates**

---

**Date:** 1/15/2013    **Status:** Inspection

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

This release was discovered while hydro-vacating for another pipeline leak incident of 12/7/12. Hydro-vaccers were exposing line prior to excavation and repair, and noticed oil bubbling out of adjacent line in same trench on 1/14/13. Repairs to both will be completed by 1/18/13. Leaking pipes are just outside, but crossing, a creek containment dike that protects hay land from spring floods. Dike will likely be breached by the repair, but will be re-built and erosion controlled as part of the repair process. All contaminated soil will be sent to Petro-Comp.

---

**Date:** 11/17/2016    **Status:** Inspection

**Author:** Wax, Pete

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site 11:17. 28 degrees, wind from the north at 10 mph, overcast. Photographs collected. Walked entire pipeline row southeast to county right-of-way (approximately 2/3 of a mile). Line looks well-shaped and seeded. No water quality issues apparent. Off site 12:02.